Sherwin	Crook	Trant	
Suermin	Creek	ITACL	

No. of Lots1 MappedAugust, 1923			
Water System Installed By Piped from nearby stream			
Road Built By Permittees			
Road Built By			
Electrical Service None Telephone None			
Access Permittees gravel road (Summers Road) from County maintained			
gravel road.			
fi.			
Lots Front On Near small stream			
Terrain In SubdivisionSloping topographhy, with light tree growth			
consisting of Aspens.			

Comments Because of the isolation of the lot from other developments and			
low density of the area, no sewer requirements have been made by the Lahont	an		
Regional Water Quality Control Board.			
*			
	_		

U. 8. DEPARTMENT OF AGRICULTURE
FOREST SERVICE
INYO NATIONAL FOREST
MAMMOTH REOREATION AREA
SHERWIN CREEK TRACT
8HEET 1
8008. 6 & 7 T. 4 8., R. 28 E. M. D. M.
OALIFORNIA

L-Uses Compass Survey Lots 1-2 & PMA Site by HH Simoson Aug 1923 Mag Decl17° Scale1°100' OALIFORNIA SW/4 SE /4 Sec. 6 SE1/4 SE1/4 Government Land ORGANIZATION SITE 24 12 Clark 1 30 Co 5 8 1 2 Ν. NW% NE% Sec. 7 Retroled by FOV 12-11 31 Corrected by EC 9-18-43